

List of figures

Figure 1.1: Last known position of the 29 deceased and two survivors	20	Figure 8.18: Location of the auxiliary fan	105
Figure 2.1: ‘Swiss cheese’ model of causation	29	Figure 8.19: Extracts from Dene Murphy’s 21 October 2010 Deputies Production Report	105
Figure 3.1: Location of the Pike River coal mine	31	Figure 9.1: Track-mounted Boart Longyear LMC75 drill rig	116
Figure 3.2: Pike River coal field cross-section	32	Figure 9.2: Bit, down-hole motor and assembly	117
Figure 3.3: Pike River coal field west–east cross-section	33	Figure 9.3: Rotating drill bit with high-pressure water	117
Figure 3.4: Pike River mine environs	36	Figure 9.4: Gas riser and slimline shaft	119
Figure 3.5: Plant location pit bottom in stone	38	Figure 9.5: Bottom of gas riser at entrance to the FAB	119
Figure 3.6: Minister of Energy and Resources, the Hon. Gerry Brownlee, Pike Chief Executive Gordon Ward, Chair John Dow and General Manager Peter Whittall at the opening of the Pike River mine	38	Figure 9.6: Email from Brian Wishart to Jimmy Cory	120
Figure 3.7: Ventilation shaft and Alimak raise	39	Figure 9.7: Gas drainage line and in-seam boreholes	121
Figure 6.1: Selected management positions held at Pike River Coal, January 2006 - 19 November 2010	59	Figure 9.8: Panel 1 production area and panel 1 area of interest for gas emissions	126
Figure 7.1: Elements of a health and safety system	70	Figure 9.9: Graph summarising total daily drainage system gas flow measurements	128
Figure 7.2: Pike safety management systems and management plan	72	Figure 10.1: Location of fixed methane sensors	134
Figure 8.1: Typical elements of a main ventilation system	82	Figure 10.2: Plan of required gas sensors at Pike River under Queensland legislation	135
Figure 8.2: Auxiliary fan	83	Figure 10.3: Location of hydro-panel sensors	136
Figure 8.3: Right-hand diagram exhausting system with force overlap	83	Figure 10.4: Control room operator’s screen on the Safegas system	136
Figure 8.4 : Current ventilation setup	89	Figure 10.5: Auxiliary fan shaft methane – 6 October 2010	137
Figure 8.5: The surface back-up fan	90	Figure 10.6: Auxiliary fan shaft methane – 8 October 2010	137
Figure 8.6: Surface fan as installed	90	Figure 10.7: Comparison bottom and top of shaft CH ₄ sensors	138
Figure 8.7: Evasé showing louvres being installed	91	Figure 10.8: References to gas trips	141
Figure 8.8: Underground fan being assembled in factory	92	Figure 10.9: Plea to stop overrides of safety circuits	142
Figure 8.9: Orientation and operation of underground fan	93	Figure 10.10: Report of lack of gas detectors	142
Figure 8.10: The surface fan after the first explosion	95	Figure 11.1: Main electrical area and zones underground	147
Figure 8.11: Extract from Dene Murphy’s 24 June 2010 Incident/Accident Form	98	Figure 11.2: Spaghetti Junction	149
Figure 8.12: Board and brattice stopping	99	Figure 11.3: Plan showing VSDs underground at Pike River	150
Figure 8.13: Board and brattice construction method	100	Figure 11.4: Structure of Pike engineering department before 24 August 2010	151
Figure 8.14: Stopping in hydro panel cross-cut	101	Figure 11.5: New structure for Pike engineering department	152
Figure 8.15: Effects of roof fall on 30 October 2010	102	Figure 12.1: Pike River’s Brunner seam	156
Figure 8.16: Hydro panel and cross-cut	103		
Figure 8.17: Ventilation inbye of the monitor panel	104		

Figure 12.2: Hydro monitor at work	157	Figure 22.1: Number of minerals and coal inspections 1991–97	272
Figure 12.3: Three-dimensional sketch of hydro panel showing height difference between intake and return and ventilation path when panel idle	157	Figure 22.2: Serious harm frequency rates	273
Figure 12.4: Guzzler ready to gather and direct water/coal mixture	158	Figure 22.3: Mining – the number of workplace assessments	275
Figure 12.5: Bird’s-eye view of the coal cutting sequence at Pike River	158	Figure 22.4: Improvement and prohibition notices	277
Figure 12.6: Cross-section of the seam in panel 1	159	Figure 22.5: Negotiated agreements and infringement notices	278
Figure 12.7: Pike’s Four-year Plan for 2010–2014	160	Figure 23.1: Salary and superannuation costs for the mining inspection function	284
Figure 12.8: Hydro-mining bonus table	161	Figure 24.1: Department of Labour organisation chart as at 19 November 2010	290
Figure 12.9: Operational preparedness gap analysis	163	Figure 24.2: Strategic leadership team as at 19 November 2010	291
Figure 12.10: Hazards arising from windblast	164	Figure 24.3: Workplace leadership team as at 19 November 2010	291
Figure 12.11: Hazard of an explosive mixture of gas in the return/through the fan	164	Figure 24.4: Highest risk sectors – injury rates	294
Figure 12.12: Drillholes in the vicinity of Panel 1	167	Figure 26.1: Considerations for the expert task force	314
Figure 14.1: Last known position of the 29 deceased and two survivors	180	Figure 32.1: Co-ordinated incident management system	347
Figure 14.2: The area of the goaf and the intersecting borehole	183	Figure 32.2: Queensland mine emergency management system	347
Figure 14.3: Gas flow path due to goaf fall	184	Figure 33.1: Example of a self-contained self-rescuer	358
Figure 14.4: Fire coming from the ventilation shaft following the fourth explosion	191	Figure 33.2: Man wearing compressed air breathing apparatus (CABA)	359
Figure 16.1: Co-ordinated incident management system	210	Figure 33.3: Recharge station for compressed air breathing apparatus	359
Figure 16.2: View of the upper FAB from outside	224	Figure 33.4: Strata Worldwide coal refuge chamber	360
Figure 16.3: View of the upper FAB looking inside	224	Figure 33.5: Northern Light Technologies two-way messenger system	363
Figure 16.4: Inside the upper FAB looking towards the entrance	225	Figure 33.6: Inertisation connection facilities	364
Figure 18.1: Comparison of work-related injury fatality rates with best-performing countries	248	Figure A.1: The commission in session at Greymouth District Court	371
Figure 18.2: Fatality rates notified to ILO	249	Figure A.2: Compulsion orders issued	372
Figure 18.3: Field inspectors (excluding mining inspectors) per 10,000 employees by jurisdiction, 2009–10	250	Figure A.3: Secretariat over the life of the commission	378
Figure 18.4: Occupational health and safety expenditure per employee by jurisdiction, 2008–09	250	Figure A.4: Secure website home page	379
Figure 19.1: New Zealand coal production	256		
Figure 19.2: Open versus underground mining	256		
Figure 20.1: New Zealand coal mine tragedies	258		